CD/PERMIT SET

COLORADO MOUTAIN COLLEGE AT GLENWOOD CENTER IN GLENWOOD SPRINGS, COLORADO

ABBREVIATIONS

A.F.F.	ABOVE FINISH FLOOR	INFO.	INFORMATION
ADJ.	ADJUSTABLE	INSUL.	INSULATION
ALT.	ALTERNATE	JST.	JOIST
A.B.	ANCHOR BOLTS	L.L.	LIVE LOAD
&	AND	LONGINT.	LONGITUDINAL
ARCH.	ARCHITECTURAL	N.I.C.	NOT IN CONTRACT
@	AT	O.C.	ON CENTER
BM.	BEAM	OPP.	OPPOSITE
BM. PKT.	BEAM POCKET	0/	OVER
BRG.	BEARING	PTD.	PAINTED
BLK'G.	BLOCKING	PERF.	PERFORATED
ВОТ.	BOTTOM	PL.	PLATE
B.F.	BOTTOM OF FOOTING	PLY.	PLYWOOD
BLDG.	BUILDING	PROP. LINE	PROPERTY LINE
B.O.	BY OWNER	REINF.	REINFORCEMENT
CAB.	CABINET	RDWD.	REDWOOD
CLG.	CEILING	REQ'D.	REQUIRED
CL.	CENTER LINE	RESIL.	RESILIENT
C.T.	CERAMIC TILE	REV.	REVISED
CLR.	CLEAR	S.M.	SHEET METAL
COL.	COLUMN	SIM.	SIMILAR
CONC.	CONCRETE	S.F. OR SQ. FT.	SQUARE FEET
CONN.	CONNECTION	STD.	STANDARD
CONT.	CONTINUOUS	STL.	STEEL
DTL.	DETAIL	STDS.	STUDS
DBL.	DOUBLE	THK.	THICK
DWL.	DOWEL	TLT.	TOILET
E.W.	EACH WAY	T.F.	TOP OF FOOTING
ELEV. OR EL.	ELEVATION	T.P.	TOP OF PLATE
EXIST'G	existing	T.L.	TOP OF LEDGE
EXT.	EXTERIOR	T.W.	TOP OF WALL
F.F.	FINISHED FLOOR	TOT.	TOTAL
F.D.	FLOOR DRAIN	T.B.	TOWEL BAR
FLR.	FLOOR	TRANSV.	TRANSVERSE
FTG.	FOOTING	TYP.	TYPICAL
FND.	FOUNDATION	U.N.O.	UNLESS NOTED OTHERWISE
GA.	GAUGE	V.I.F.	VERIFY IN FIELD
G.L.	GLU-LAM	VERT.	VERTICAL
GWB	GYPSUM WALL BOARD	V.W.C.	VINYL WALL COVERING
G.S.	GAS STUB	W.C.	WATER CLOSET
HB.	HOSE BIB	W.H.	WATER HEATER
HT.	HEIGHT	W.P.	WATERPROOF
HK.	HOOK	W.R.	WATER RESISTANT
HORIZ.	HORIZONTAL	WIN.	WINDOW
HYD.	HYDRANT	W/	WITH
		WD	WOOD

STATE OF COLORADO BUILDING REQUIREMENTS

CODES AND STANDARDS: 2021 IBC, IEBC, IECC, IFGC, IMC, IPC, IFC, 2023 NEC AND CMERSRC AS ADOPTED BY THE STATE OF COLORADO

ACCOUNT #: R311938

PARCEL ID: 218516100084

LEGAL DESCRIPTION: SECTION: 16 TOWNSHIP: 6 RANGE: 89; TRACT OF LAND IN NENE AMENDED PLAT OF ESPERANZA SUBDIVISION (REC 302942)

LOT AREA: 4.02 ACRES / 175,111 SF

USE OF BUILDING: POST SECONDARY EDUCATION, B-OCCUPANCY

TYPE OF WORK: REMODEL

TYPE OF CONSTRUCTION: 5B **GROUND SNOWLOAD:** 50 PSF

SEISMIC DESIGN CATEGORY: B

WEATHERING PROBABILITY FOR CONCRETE: SEVERE

TERMITE INFESTATION PROBABILITY: SLIGHT TO MODERATE

WIND SPEED: 115MPH

DECAY PROBABILITY: NONE

WIND EXPOSURE: C

FROST DEPTH: 36IN.

WINTER DESIGN TEMPERATURE: MINUS 2F

AIR FREEZING INDEX: 1500. ICE SHIELD UNDERLAYMENT REQUIRED.

MEAN ANNUAL TEMPERATURE: 48F

CLIMATE ZONE: 6 (GARFIELD COUNTY)

SKYLIGHT INSULATION: U-FACTOR = 0.5 MIN, SHGC 0.4 MIN, CURB INSULATED TO R-5 (2021 IECC C402.2.1.5)

CONTACT INFORMATION

ARCHITECT: Land+Shelter, Inc. PO Box 550 (Mail) / 16 North 4th St. (Office) Carbondale, CO 81623 Contact: Kendra Oester Email: kendraoester@landandshelter.com

OWNER:

Colorado Mountain College 802 Grand Avenue (Admin Offices) Glenwood Springs, CO 81601 Contact: David Negrete, Asst. Director of Facilities Phone: 719-486-4220 Email: dnegrete@coloradomtn.edu

Cell Phone: 360-259-1038

STRUCTURAL ENGINEER: SGM Engineering 118 W Sixth St., Suite 200 Glenwood Springs, CO 81601

Phone: 970-384-9035 Contact: John E. Partch, PE Email: johnp@sgm-inc.com

MEP ENGINEER:

Big Horn Consulting Engineers 386 Indian Road Grand Junction, CO 81501 Phone:970-241-8709 Contact: Mark Harrington Email: mark@bighorneng.com

DRAWING INDEX

GENERAL: COVER SHEET - PROJECT INFO. A1.0 A1.1 LIFE SAFETY & AREA OF WORK **ARCHITECTURAL:** A3.0 EXISTING & DEMO PLAN A3.1 **NEW PLAN**

> A3.2 **ROOF PLAN** DEMO AND NEW RCP A3.3 A5.0 BUILDING SECTIONS A6.0 INTERIOR ELEVATIONS AND ENLARGED PLANS

A7.0 DETAILS A10.0 SCHEDULES

STRUCTURAL: GENERAL NOTES AND ANNOTATIONS \$102

ELECTRICAL COVERSHEET EO-1 E1-1 D LIGHITING- DEMO FLOOR PLAN E1-1 N LIGHTING FLOOR PLAN

E2-1 D ELECTRICAL - EXISTING FLOOR PLAN ELECTRICAL-FLOOR E2-1 N E3-1 ELECTRICAL- DETAILS M0-0 MECHANCIAL COVER SHEET

FIRST FLOOR WALL AND ROOF FRAMING PLAN

M1-0 MECHANCIAL NEW AND DEMO PLAN M1-1 MECHANICAL - PLAN MECHANCIAL SCHEDULES PO-1 PLUMBING COVER SHEET P1-1 PLUMBING PLAN

PLUMBING SCHEDULES

NOTICE: DUTY OF COOPERATION Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction

> arising out of such changes. CD/PERMIT SET JANUARY 7TH, 2025 **Revisions**

16 North 4th Street, Carbondale, CO 81623 t 970.963.0201 info@landandshelter.com

costs. A failure to cooperate by a simple notice to the architect

shall relieve the architect from responsibility for all consequences.

Changes made from the plans without consent of the architect are

unauthorized and shall relieve the designer from all consequences

Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

COVER SHEET - PROJECT INFO.

Sheet Number:


CLASSROOM 2 INTERIOR

PROJECT DESCRIPTION

REMODEL OF A PORTION OF THE GROUND LEVEL FLOOR OF THE CMC GLENWOOD CENTER INCLUDING HVAC AND FINISH WORK. THE REMODEL ENCOMPASSES 3030SF AND INCLUDES SOME REMOVAL AND ADDITION OF NON-STRUCTURAL INTERIOR PARTITIONS. THE MAIN PROGRAMMATIC PURPOSE OF THE REMODEL IS TO ADD A CLASSROOM TO THE EXISTING EARLY CHILDHOOD EDUCATION CENTER ON THE MAIN LEVEL, WHICH IS CURRENTLY A SINGLE CLASSROOM. AFTER THIS RENOVATION IT WILL BE A TWO -CLASSROOM EDUCATION CENTER WITH A THIRD FLEXIBLE SPACE WITH LAUNDRY AND STORAGE. THE NEW CLASSROOM INCLUDES TWO BATHROOMS FOR CHILDREN. THE RENOVATION INCLUDES SOME REORGANIZATION OF EXISTING SMALL OFFICES AND A SKYLIGHT AS WELL. THE SKYLIGHT IS REPLACING AN OLDER SKYLIGHT, WHICH WAS ORIGINAL TO THE BUILDING, BUT REMOVED AT SOME POINT IN THE HISTORY OF THE BUILDING, DATE








LOCATION MAP

ENTRY INTERIOR




FLOOR AREA SU	JMMARY
FLOOR AREA SUMMARY	
TOTAL BUILDING AREA (GROSS)	31,870 SF
renovation:	3,013 SF
MINI COLLEGE	2,899 SF
RECEPTION OFFICE	114 SF

OUTDOOR PLAYSPACE PROVIDED 1" = 10'-0" 3


2021 INTERNATIONAL EXISTING BUILDING CODE: LESS THAN 50% OF BUILDING IN AREA OF WORK; TYPE II ALTERATION

CODE NOTES:



OCCUPANCY/EGRESS								
NAME	AREA	OCCUPANCY TYPE	AREA PER OCCUPANTS	OCCUPANTS	MAX ACTUAL TRAVEL	MAX ALLOWABLE TRAVEL	CODE NOTES	
CLASSROOM 1	779 SF	E-EDUCATION	EDUCATION - 20 NET	39	102'-10"	250'-0"		
CLASSROOM 2	620 SF	E-EDUCATION	EDUCATION - 20 NET	31	117'-11"	250'-0"		
ENTRY	85 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	16'-3"	300'-0"		
FLEX	551 SF	E-EDUCATION	EDUCATION - 20 NET	28	130'-7"	250'-0"		
MINI-COLLEGE OFFICE	80 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	81'-6"	300'-0"		
RECEPTION OFFICE	114 SF	B-BUSINESS	BUSINESS - 150 GROSS	2	69'-5"	300'-0"	OCCUPANCY SET BY NUMBER OF DESK CHAIRS - HIGHER THAN REQUIRED BY OCCUPANCY AREA	
SERVER	122 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	96'-3"	300'-0"		
STORAGE	115 SF	B-BUSINESS		1	85'-9"	250'-0"	ACCESSORY OCCUPANCY	
				104				

OCCUPANCY/EGRESS								
NAME	AREA	OCCUPANCY TYPE	AREA PER OCCUPANTS	OCCUPANTS	MAX ACTUAL TRAVEL	MAX ALLOWABLE TRAVEL	CODE NOTES	
CLASSROOM 1	779 SF	E-EDUCATION	EDUCATION - 20 NET	39	102'-10"	250'-0"		
CLASSROOM 2	620 SF	E-EDUCATION	EDUCATION - 20 NET	31	117'-11"	250'-0"		
ENTRY	85 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	16'-3"	300'-0"		
FLEX	551 SF	E-EDUCATION	EDUCATION - 20 NET	28	130'-7"	250'-0"		
MINI-COLLEGE OFFICE	80 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	81'-6"	300'-0"		
RECEPTION OFFICE	114 SF	B-BUSINESS	BUSINESS - 150 GROSS	2	69'-5"	300'-0"	OCCUPANCY SET BY NUMBER OF DESK CHAIRS - HIGHER THAN REQUIRED BY OCCUPANCY AREA	
SERVER	122 SF	B-BUSINESS	BUSINESS - 150 GROSS	1	96'-3"	300'-0"		
STORAGE	115 SF	B-BUSINESS		1	85'-9"	250'-0"	ACCESSORY OCCUPANCY	



CHANGE IN ROOM OCCUPANCY TYPE: CLASSROOM 2 AND FLEX ARE CHANGING FROM B-BUSINESS TO E-EDUCATION DUE TO THE OCCUPANT AGE SHIFT.


NEW OCCUPANT LOAD: THESE ROOMS ARE NOT SHIFTING IN OCCUPANT LOAD, GOING FROM A CLASSROOM USE TO A CLASSROOM USE. PLUMBING CALCS & OCCUPANTS EGRESSING TO BUILDING FRONT DOOR ARE NOT CHANGED. CLASSROOM 1 WAS ORIGINALLY E-EDUCATION OCCUPANCY AND IS NOT CHANGING.



NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.


CD/PERMIT SET JANUARY 7TH, 2025 **Revisions**



Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

LIFE SAFETY & AREA OF WORK

Sheet Number:





16 North 4th Street, Carbondale, CO 81623 t 970.963.0201 info@landandshelter.com

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the

architect compounds misunderstanding and increases construction

costs. A failure to cooperate by a simple notice to the architect

shall relieve the architect from responsibility for all consequences.

Changes made from the plans without consent of the architect are


unauthorized and shall relieve the designer from all consequences

NOTICE: DUTY OF COOPERATION

arising out of such changes.

CD/PERMIT SET
JANUARY 7TH, 2025

Revisions



EVOVAIIC NVE SET

1402 BLAKE AVE CD/PERMIT SET

Somblea MAR Somblea MAR ANDREA KORBER 401268 ANDREA ANDR

Job Site:
1402 BLAKE AVE
GLENWOOD SPRINGS,
_COLORADO 81601

EXISTING & DEMO PLAN

Sheet Number:

FLOOR PLAN KEY:

EXISTING / EXISTING TO REMAIN

EXISTING COLUMN TO REMAIN (APPROX. LOCATION)

PROPOSED NEW PLUMBING FIXTURE (SEE PROPOSED PLAN FOR FIXTURE TYPES ALL ROOMS)

A3.0

lame.rvt 1/8/2025 3:25:28 РМ

NORTH COMPUTER

EXTENDED AREA OF

CLASSROOM 1

EXISTING

CLASSROOM 1
BLONDE LVT

BRICK

PLAYGROUND 3,150 SQFT

42 CHILDREN ALLOWED IN OUTDOOR AREA PER CDHS

CARPET TILES

XX

CONC.

HALL

SERVER

EXISTING PLAN
3/16" = 1'-0"
1

GREY = NOT IN SCOPE

CHERRY LVT

DASH = LINE OF 2ND FLOOR WALL ABOVE

EXISTING RECEPTION DESK

CHERRY LVT

GREY = NOT IN SCOPE

CHERRY LVT

CHERRY LVT


DAYCARE OFFIC

__RECEPTION OFFICE

STORAGE & PLAY NOOK

CARPET

LOFT ABOVE



ARCHITECTURE AND PLANNING

16 North 4th Street, Carbondale, CO 81623

NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

CD/PERMIT SET JANUARY 7TH, 2025 Revisions


401268

Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

NEW PLAN

Sheet Number:

EXISTING ROOF CONDITION ABOVE MINI COLLEGE, SEE DRAWING FOR PHOTO LOCATION REFERENCE



Land+Shelter

Land+Shelter
ARCHITECTURE AND PLANNING
16 North 4th Street, Carbondale, CO 81623
t 970.963.0201 info@landandshelter.com

NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

CD/PERMIT SET JANUARY 7TH, 2025 Revisions

 \triangle

AC MINI COLLEGE REVOVATIC 1402 BLAKE AVE CD /PERMIT SFT


Schola Chile ANDREA * 401268 * ANDREA *

Job Site:
1402 BLAKE AVE
GLENWOOD SPRINGS,
COLORADO 81601

ROOF PLAN

Sheet Number:

A3.2



MATERIAL LEGEND

<u>LIGHTING FIXTURE KEY</u>

RECESSED CAN

WATERPROOF CAN

DIRECTIONAL RECESSED CAN

BATH FAN

s SMOKE DETECTOR

(co) CARBON MONOXIDE DETECTOR



NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

CD/PERMIT SET JANUARY 7TH, 2025 Revisions

REV ER $\mathbf{\Omega}$ **_**

0

KORBER 401268

Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

DEMO AND NEW RCP

Sheet Number:

NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.


CD/PERMIT SET JANUARY 7TH, 2025 **Revisions**


Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

BUILDING SECTIONS

Sheet Number:

N/S SECTION 1





Land+Sholton

ARCHITECTURE AND PLANNING
16 North 4th Street, Carbondale, CO 81623
t 970.963.0201 info@landandshelter.com

NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is

construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

CD/PERMIT SET JANUARY 7TH, 2025 Revisions

<u>Z</u>

402 BLAKE AVE D/PERMIT SET

Schohea WAR Schohea WAR ANDREA KORBER 401268 ANDREA KORBER ANDREA ANDR

Job Site:
1402 BLAKE AVE
GLENWOOD SPRINGS,
COLORADO 81601


INTERIOR ELEVATIONS AND ENLARGED PLANS

Sheet Number:

A6.0



These images serve as the basis for the design of the artwork on the wall between the skylight and the ACT ceiling. The concept is to depict Colorado wildlife looking down from the opening. The exact design is subject to owner approval if the add/alternate is selected. Each of the 4 walls is approximately 52" tall and 72" wide. The design can be painted on, printed on, applied vinyl or approved equal.





ARCHITECTURE AND PLANNING 16 North 4th Street, Carbondale, CO 81623 t 970.963.0201 info@landandshelter.com

NOTICE: DUTY OF COOPERATION

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

CD/PERMIT SET JANUARY 7TH, 2025 **Revisions**

Ш


 $\mathbf{\Omega}$

0


ADD/ALT- SKYLIGHT DETAIL
1 1/2" = 1'-0"

5





CORNER OF EXISTING SKYLIGHT OPENING - WHITE PAINTED DECKING & TRUSS TO STAY, DEMO SILVER DECKING CAP





ADD/ALT- SKYLIGHT

3/4" = 1'-0"


4







2" THICK HIGH DENISTY FOAM CUSHION, UPHOLSTERED. FRAME CONSTRUCTION OUT OF (2) 3/4" FINISH GRADE BIRCH PLAYWOOD, LAMINATED, FINSHED W/ DURABLE, CLEAR, LOW VOC, FINISH SUCH AS SHEENPLUS. TYP, ALL BENCH CONSTRUCTION. - INTERMEDIATE SUPPORT, SPACE EQUALLY.



BENCH @ ENTRY - SECTION
1 1/2" = 1'-0"
1

Job Site: 1402 BLAKE AVE GLENWOOD SPRINGS, COLORADO 81601

DETAILS

401268

Sheet Number:

GWB to ACT TRANSITION
1 1/2" = 1'-0"
3


SHOWN ON 1/A3.3

TO CEILING TILE; PAINT TO MATCH CEILING GRID


- EXTEND ACT. CEILING TO CORNER AS

BENCH @ ENTRY - FRONT
1 1/2" = 1'-0"
2


*NOTE: ALL DOOR HARDWARE TO BE LEVER STYLE IN COMPLIANCE WITH ADA GUIDELINES. MATCH EXISTING IN REST OF BUILDING. REUSE DOORS & HARDWARE AS MUCH AS POSSIBLE.



	WINDOW SCHEDULE									
				FRAME SIZE						
MARK	TYPE	RM#	ROOM NAME	FRAME WIDTH	FRAME HEIGHT	SASH OPERATION	GLAZING	Comments		
W127A	W1	128	FLEX ROOM	4'-0"	4'-0"	DIRECT SET				
W127B	W1	127	OFFICE	3'-0"	2'-0"	DIRECT SET				
W127D	W1	127	OFFICE	3'-0"	2'-0"	DIRECT SET				
W127C	W2			23'-10"	4'-0"	CURTAIN WALL				
W129	W3	129	CLASSROOM #2	5'-9 1/2"	5'-9 1/2"	SKYLIGHT, NON OPERABLE	TEMPERED	ADD/ALT		



ROOM FINISH SCHEDULE									
RM #	Room Name	Floor	Floor Finish Color	Base	Wall	Wainscott	Ceiling	Comments	
127	OFFICE	LVT	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT2, DETERMINE ON SITE		A.C.T., REUSE AS MUCH AS POSSIBLE		
128	FLEX ROOM	LVT	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT1, DETERMINE ON SITE		A.C.T., REUSE AS MUCH AS POSSIBLE		
129	CLASSROOM #2	LVT	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT1, DETERMINE ON SITE		A.C.T., REUSE AS MUCH AS POSSIBLE		
130	ADA CHILD RESTROOM 1	TILE	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT3, DETERMINE ON SITE	TILE TO 48"	HARD LID, GWB, PTD.		
131	CHILD RESTROOM 2	TILE	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT3, DETERMINE ON SITE	TILE TO 48"	HARD LID, GWB, PTD.		
132	HALL	EXISTING EXPOSED CONCRETE TO REMAIN		RUBBER COVE	PTD PT1, DETERMINE ON SITE		GWB, PTD & A.C.T.		
133	SERVER	EXISTING EXPOSED CONCRETE TO REMAIN		RUBBER COVE	PTD PT4, DETERMINE ON SITE		A.C.T. & OPEN, REUSE AS MUCH AS POSSIBLE		
134	STORAGE	EXISTING EXPOSED CONCRETE TO REMAIN		RUBBER COVE	PTD PT4, DETERMINE ON SITE		A.C.T, REUSE AS MUCH AS POSSIBLE		
135	CLASSROOM #1	FLOORING TO REMAIN EXCEPT FOR CARPET; REPLACE CARPET	BLONDE TO MATCH	RUBBER COVE	PTD PT1, DETERMINE ON SITE		OPEN STRUCTURE TO REMAIN, NO WORK		
136	CHILD TOILET	EXISTING TO REMAIN		RUBBER COVE	PTD PT3, DETERMINE ON SITE		HARD LID, GWB, PTD.		
137	CHILD TOILET	EXISTING TO REMAIN		RUBBER COVE	PTD PT3, DETERMINE ON SITE		HARD LID, GWB, PTD.		
138	ENTRY	LVT, PATCH AS NECESSARY	BLONDE TO MATCH CLASSROOM 1	RUBBER COVE	PTD PT1, DETERMINE ON SITE		OPEN STRUCTURE TO REMAIN, NO WORK		
139	NEW OFFICE	LVT	COPPER TO MATCH LOBBY	RUBBER COVE	PTD PT5, DETERMINE ON SITE		A.C.T., REUSE AS MUCH AS POSSIBLE		



- HEADER PER STRUCT.

- STOREFRONT, SEAL


FOR SOUND

STOREFRONT HEAD

1 1/2" = 1'-0"


3

INT.



STOREFRONT JAMB 2

1 1/2" = 1'-0"



DOOR - INT. SWING HEAD

1 1/2" = 1'-0"

6 DOOR - INT. SWING JAMB

1 1/2" = 1'-0"

5 DOOR - INT. SWING SILL

1 1/2" = 1'-0"

4

- GWB RETURNS, TYP.; CAULK GAP BETWEEN STOREFRONT & GWB

— SEAL STOREFRONT FOR SOUND

— DOUBLE METAL STUDS

INT.

1/2" OVERHANG—

— SEAL STOREFRONT FOR SOUND

— DOUBLE METAL STUDS

OR APPROVED EQUAL.

– 1" POPLAR, PAINTED, RETURNS,TYP.

; CAULK GAP BETWEEN AT STOREFRONT, TYP.

— ADD ALT, PREMANUFACTURED CUBBIES, 3' TALL, W/ RICHLITE 1" BLACK DIAMOND COUNTER TOP

Release of these plans contemplates further cooperation among the owner, his or her contractor, and the architect. Design and construction are complex. Although the architect and his/her consultants have performed their services with due care and diligence, they cannot guarantee perfection. Communication is imperfect and every contingency cannot be anticipated. Any ambiguity or discrepancy discovered by the use of these plans shall be reported immediately to the architect. Failure to notify the architect compounds misunderstanding and increases construction costs. A failure to cooperate by a simple notice to the architect shall relieve the architect from responsibility for all consequences. Changes made from the plans without consent of the architect are unauthorized and shall relieve the designer from all consequences arising out of such changes.

Land+Shelter


16 North 4th Street, Carbondale, CO 81623


t 970.963.0201 info@landandshelter.com

CD/PERMIT SET JANUARY 7TH, 2025 Revisions

NOTICE: DUTY OF COOPERATION







STUD WALL, 16" O.C. - SOUND BATT, MIN R-13 ___ 5/8" GWB, PTD. *NOTE: ALL WALLS GO TO UNDERSIDE OF DECK. FRAME OUT AROUND OPEN JOISTS AS NECESSARY.

2x6 INTERIOR WALLS
1 1/2" = 1'-0"

SCHEDULES

401268

0

Sheet Number:

Job Site:

1402 BLAKE AVE

GLENWOOD SPRINGS, COLORADO 81601

A10.0